Zone	Division	Total number of non functioning piped water supply schemes									Total
		Due to Theft of pump/motor/transform er/pipes	Due to Old Age of the Scheme	Intra/Inter Village rivalry/dispute over sharing of water sources/land disputes/Damage by miscreants	Drying up of sources./C hange of River course			Due to coal mining, quality problem	Damage due to wild animals	Other reasons	number of non functioning schemes
3	4	5	6	7	8	9	10	11	12	13	14
Garo Hills	Resubelpara				3	3				0	3
Garo Hills	Simsanggiri				2	2				0	_
Garo Hills	Baghmara	3	6		1	3				0	
Garo Hills	Tura		4		1	2	2	2			9
Garo Hills	Tura North	7			2	2 3				0	
Garo Hills Total		10	10	C	9	8	2	2	0	0	39
Jaintia Hills	Electrical Shillong	0			Ī	Ī			T	0	0
Jaintia Hills	Jowai	4		1	7	,		4	1		16
Jaintia Hills Total		4	0	1	7	0	C)	1 0	0	16
Khasi Hills	GSWS Divn No -I	3					1			0	4
Khasi Hills	GSWS Divn No -II	0								0	0
Khasi Hills	Investigation	1		1						1	3
Khasi Hills	Electrical Mawphlang	0						1	1	0	1
Khasi Hills	S&D	0					1			0	1
Khasi Hills	Cherrapunjee	10			1					0	11
Khasi Hills	Hills	5		1						0	
Khasi Hills	Nongpoh	6	6	_	1					5	18
Khasi Hills	Nongstoin	25	8		3	3			3	2	
Khasi Hills	Mawkyrwat	17	1	4		2	2	? 3	3 2	2	33
Khasi Hills Total		67	15	6	5	5	4	. 4	1 5	10	118
Grand Total		81	25	7	21	10	6	8	5	10	173
Percentage		46.82%	14.45%	4.05%	12.14%	5.78%	3.47%	4.62%	2.89%	5.78%	100.00%